

Hugo Anderson, Superintendent
Kim Vincent, Secretary
Staci Auck, Business Manager



108 6th Street E.
Hobson, MT 59452
[406] 423-5483
Fax-[406] 423-5260

hugo.anderson@hobson.k12.mt.us

www.hobson.k12.mt.us

Hobson School

Hobson Schools has asbestos inspections in compliance with state and federal laws. The latest inspection report is included on the school website. For explanation or to review this or other inspection reports, contact superintendent Hugo Anderson.

In short, all of the asbestos used for any pipe insulation in the basement, boiler room, or elsewhere has been abated years ago thanks to a grant that Mrs. Bergstrom wrote. There is a great deal of 9" tile throughout the building that is regularly inspected by Amanda Barnes and Mr. Anderson to ensure that it does not have any cracks or damage. As long as it is either covered with carpet or sealed with a wax coating, it poses absolutely no hazard what-so-ever. The only potential risk would include if it were to be damaged and in a 'friable' state where dust particles would become airborne.

<http://www.asbestos.com/abatement/friable/php>